


STATE OF UTAH  
DEPARTMENT OF NATURAL RESOURCES  
DIVISION OF OIL, GAS AND MINING  
355 West North Temple  
3 Triad Center, Suite 350  
Salt Lake City, Utah 84180-1203  
Telephone: (801) 538-5340  
Fax: (801) 359-3940



ANNUAL REPORT OF MINING OPERATIONS

The informational requirements of this form are based on provisions of the Mined Land Reclamation Act, Title 40-8, Utah Code Annotated 1953, as amended, and the General Rules as promulgated under the Utah Minerals Regulatory Program. An operator conducting mining operations under a Notice of Intention must file an annual operations and progress report (FORM MR-AR) with the Division.

I. General Information

1. Report Time Period: From (mo./yr.) 1-1-95 To (mo./yr.) 12-31-95
2. DOGM File Number (Mine No): SM/015 / 041
3. Mine Name: DKG Quarry
4. Mineral(s) Mined (or permitted to mine): Gypsum
5. Type of mine ☒ Surface Mine or ☐ Underground Mine
6. Legal Description (Location of Lands Affected):  
NE 1/4, SW 1/4, Section 29, Township 22S, Range 9E  
NE 1/4, SW 1/4, Section 29, Township 22S, Range 9E  
1/4, 1/4, Section , Township , Range
7. Name of Operator or Company: Diamond K Gypsum, Inc./Phillip Palmer opr
8. Permanent Street Address: 1600 So Redview Dr P.O. Box 35  
City, State, Zip: Richfield, Ut 84701  
Phone: 801-896-8870
9. Company Representative (or designated operator):  
Name: Phillip Palmer  
Title: Owner  
Business Address: 1600 So Redview Dr  
City, State, Zip: Richfield, Ut 84701  
Phone: 801-896-8870

☒ Please check if any of the above information has changed since previous year.

II. Mining and Reclamation \*\* Incorporated 1-1-96 (effective date) New Fed I.D. #87-0548720

1. Was the mine active during the past year? Yes ☒ No ☐
2. If active, how much ore or mineral was mined? 17480.44 Tons

3. How much **additional acreage** was disturbed during the past year? 2 acres
4. Briefly describe any new or additional surface disturbances that occurred during the past year. This description should include the type of work performed, and volume of material moved.  
2 acres to the Southwest of the existing disturbance was  
opened for mining. The top soil was removed and stock-  
piled. Approximately 10,000 tons were removed.
5. How much acreage was **reclaimed** during the past year? 5 acres
6. Briefly describe the reclamation work performed during the past year. This description should include methods employed, and an evaluation of the results.  
In October we performed reclamation replacing the bottom  
soil and then the top soil was applied. We then reseeded  
using your recommended soil mixture. It is receiving the  
winter moisture and looks good.
7. What is the **total disturbed acreage** at years end? 4 acres
8. Briefly summarize any mining and/or reclamation plans for the upcoming year.  
1. To continue in the portion now disturbed.  
2. Mine out the disturbed area and reclaim that area.

**NOTE:** Section III., "Additional Information" applies only to large mining operations.

### III. Additional Information

1. An updated surface facilities map should be attached if there have been significant changes since the previous map was submitted.
2. Any monitoring results or other reports that are required under the terms of the approved notice of intention should also be attached.

### IV. Signature Requirement

I hereby certify that the foregoing is true and correct.


Name (Typed or Print):

Phillip Palmer

Title of Operator:

Owner/Operator

Signature of Operator:



Date:

1-26-95

\* \* In reference to the Corporation:

Phillip Palmer	Pres.,CEO	234 North 500 West	Richfield, Ut 84701
Karen Palmer	V.P.,CFO	234 North 500 West	Richfield, Ut 84701
Kristi Palmer	Sec	1681 N Woodland Dr,	Provo, Ut 84604

Directors:

Phillip Palmer  
Karen Palmer  
John Z Reeves. Jr.  
(All Stockholders)

Change of address:

Diamond K Gypsum, Inc.  
P.O.Box 35  
Richfield, Ut 84701

Physical address:

1600 So Redview Dr  
Richfield, Ut 84701